State of Maryland
Department of the Environment

Hazardous and Solid Waste Mgmt. Administration

2500 Broening Highway Baltimore, Maryland 21224 Tel. No. (301) 631-3400

MINIATION FINISHING

moD98,5386143

Generator Inspection.

FI 910114 PG 614 Inspector Frantz Date 1/14/91
Facility Name Mid Atlantic Finishing
Address 4656 Addison Rd.
Capitol Heights, Md. 20743
Facility's EPA I.D. No
Facility's Representative Ray Patel
Facility's Telephone No. (301) 322-2233
* Facility has apparently not notified EPA/MDE of generator status and is using a provisional number on manifests.
Section A - CHS Generation (COMAR 26.13.02)
1. Does the facility generate CHS as defined in COMAR 26.13.02.1019 (ignitable, corrosive, reactive, EP toxic or RCRA listed)? If Yes, list CHS and explain in Section G. Foo6
2. Is characteristic determined by methods specified in COMAR 26.13.02.1114? If No, what method was used? AttachedKnowledge
3. Is the facility a small quantity, or large quantity generator? How much? large quantity ~ 5000 lbs Foo6 sludge every three months
4. If small quantity, does the generator meet requirements as defined in COMAR 26.13.02.05?YesNo WAR Explain the method of disposal in Section G.
Section B - Manifest (COMAR 26.13.03)
1. Is manifest system in operation for off-site shipment?

Page 1 of $\frac{3}{}$

2. I	Manifest include the following information: Manifest document number Generator's name, address, telephone no. Generator's EPA I.D. No. Transporter's name and EPA I.D. No. State of MD transporter's certificate no. State of MD driver's certificate no. Alternate transporter's name and EPA I.D. No. Designated TSDF name, address, & EPA I.D. No. Alternate TSDF name, address, & EPA I.D. No. Description of the waste as required by DOT Total quantity of each hazardous waste by units of wt. or volume and type & no. of containers Shipment Date Is proper certification noted on manifest	Yes	NoNoNoNoNoNoNoNoNoNoNo
	* using provisional number.		
Sec	tion C - Pre-Transport Requirements (COMAR 26.13	.03.05)	
1. 2.	Is each container marked with date of accumulate labels not accessible to inspection. Has any waste been stored over 90 days?	ion? Yes Yes	No
3.	If Yes, how much Are containers in good condition? If No, explain	✓Yes	No
4.	Are containers properly labeled? Is satellite accumulation no more than 55 gallor	Yes	No
	hazardous waste or 1 qt. of acute hazardous was	te? Yes	No.M
	If No, how much		
Sec	tion D - Recordkeeping and Reporting (COMAR 26.1	3.03.06)	
 2. 3. 	Does the generator have signed copies of all man for the previous three years? Does the generator have copies of annual report the previous three years? Did the generator file any exception report dur last three years?	Yes for Yes	No
Sec	tion E - Special Conditions (COMAR 26.13.03.07)		
1.	Did the generator export or import any hazardou to and from a foreign country? If Yes, explain in Section G.	s waste Yes	No

Page 2 of 3

	2.	Did the generator comply with State of Maryland regulations? If No, explain in Section G.	's Yes	No N/
	Sec	ction F - General Requirements (COMAR 26.13.05)	`	
	1.	Does the facility meet the general facility star required in COMAR 26.13.05 which include but not to the following: Personnel training (COMAR 26.13.05.02G) Aisle space (COMAR 26.13.05.02I) Preparedness and preventive program (COMAR 26.13.05.03) Written contingency plan and emergency procedures (COMAR 26.13.05.04) Needs update Containment system (COMAR 26.13.05.09) If the answer is No, explain in Section G.	t limite Yes Yes Yes	d no no
	2.	Has the facility submitted a copy of the contine and emergency procedures to the Department?	gency pl	an No
	3.	Does the facility lack in any standard other the mentioned, as a minimum requirement established COMAR 26.13.05?		bove No
		ction G - Report of Observation cardous wastes	1	
-		Al - Foob - wastewater treatment sludge	-	
	,	Foo6-ion exchange resin beds from the	atment o;	f wastewate
		F1. Company has no training records for F2. Company is updating contingency plated.	person	inel. 'submit
-	_ <	see also attached pages.		
			age 3 of	: <u>3</u>



Department of the Environment Hazardous and Solid Waste Management Administration 2500 Broening Highway, Baltimore, Maryland 21224

p. 1 of 2

Report of Observations

Type of Inspection/Observations: Compliance Evaluation Inspection Date 1/14/90
Facility Name: Mid-Atlantic Finishing Juc.
Remarks: The furth Mr. Ray Patel Chemist, Conyany also
sepresented by Bob Mason and 5º Bob Magia.
Company is involved in metal plating for military
und commercial customers, (including automotive). Metals
pluted include ginc cadmium, copper ten tin/ginc
nickel iron gold silver, and brass. Overation is divide
between of building and new line on lower level.
Waste rense waters from old building (Cr and CN-bearing
are just piped through I double wall pic to an ion
exchange resin seisten which removes Cr x CN. Cleaned
water is reused in rinse tanks. I Two sets of
resen beds are sured by MAF, with one being
recenerated at any time by Compliance Rocycling
of Levettoun Pa- Beds are shipped under HW
(manifest the (FOOG) to regeneration.
Waste since waters from new line are
treated in waste water treatment segotem on site
to destroy CN and precipitate Cr. Supernatant
from Clarifier is sought in Auston. Water from
Oranised from Mischarged to WSSC.
Water smoored from sludge in slute & frame
Ester is re-introlled ento worth Sunten in
1) also used to treat any spillage from wating
to tanks which is collected by sumps.
Discharge to WSSC is tested daily leg MAF.
Quarterly testing is done by independent Rab with
spelet namples unakinged in-house. WSSC wellso
sur see discharge.
Sleedge from plate + frame bilter is removed
every 90 days by Clean Harbors. 16 dryms of
+ook are advantiles pickup this afternoon, Lant
shippent was on 10/12/90 (14 driums)
Observer: Douglas E-Frant Person Interviewed: 18772
MDÉ 111 REV. 1/11/88
osa quitas



Department of the Environment Hazardous and Solid Waste Management Administration 2500 Broening Highway, Baltimore, Maryland 21224

Report of Observations

page 2 of 2

	cility Name:
116	Betrind plant a 40' shipping container is used to
	store dry chemicals used in slating. a storage
	room of Con north end of building also stores
	now materials mostly in small containers
_	(5 gallon on less).
	Following cereas were noted to be med
	correction:
_	1. Company needs a permanent EPA 1D number
_	will be sent to Mr. Patel.
_	2. LDR paperwork should be kept with appro
\ \	munifiest.
<i>E</i> —	3. HW drums in storage area should be
	Pabelled with accumulation date & "Hazardon
	(varle" so that labeling is visible.
	4. Those workers involved with hundling of
_	bigardous waste should receive for training
_	in compliance with regulations. Go cording to
_	Mr. Patel, plans are liveing made to have
_	training done.
	5. Contingency Plan needs updating. Once
	undated da copy should be Osent to this
	writer.
_	
_	• •
_	
) _	
<i>(</i>	
_	10-11/11/
	poserver: Douglas E. Frantz Person Interviewed:

GSA No. 0246-EPA-OT

Please refer to the Instructions for Filing Notification before completing this form. The information requested here is required by law (Section 3010 of the Resource Conservation and Recovery Act).



Notification of Regulated Waste Activity

Date Received (For Official Use Only)

United States Environmental Protection Agency

٦,١.	Insta	allati	on's	EP/	ID	Nun	nber	(Ma	rk 'X	' In t	he a	ppro	pria	ite b	ox)														
Ť	∇	A. F	rst N	lotif	cati	on	THE STATE OF THE S] в.	Sub	seq	uent	Not	ifica	tion					Т	C.	Insta	llatio	T			ımbe	$\overline{}$		
<u> </u>	<u> </u>					4	200	-			e iter	-	بسيانيا		-		M	D		10	0	- -0	-[-	_) = 2	2=1	=0	3	
II.	Nan	ne o	Ins	talla	ion	(Inc	lude	con	npan	y an	d sp	ecifi	c si	e na	me)			\(\text{\text{\$I\$}} \)	ha (2L	9	18	5	38	6	14	<u>"3</u> _		
M	I	D		Α	Τ	L	Α	N	Т	I	Ċ		F	Ι	N	I	S	Н	I	N	G	,		Ι	Ν	C.			
-		CHICAGO MEN	n of	Inst	allat	ion	(Phy	sical	ado	iress	not	P.O.	. Bo	x or	Rou	te N	umb	er)	>_			:			•		545	la 400 mm mai	
- mlassi	reet		[]		Λ	Б	Б	[-]	<u>ر</u>		NT	$\overline{}$	D		Γ,	<u> </u>		ı	r -					Γ	Γ	T The same of the			
4	6 reet	5	6	ed)	Α	D	D	I	S	0	N		R	0	A	D		Ļ	<u> </u>		,		L	Ļ.,	<u> </u>		1907-1400	7715	
		(00.		i		:		Į.				·	a t	-	İ		-						r –	Γ	Π			and the state of t	
C	ty or	r Tov	لــــا vn			-	<u> </u>	لــــا	7.5.	ب	ليبا		•		<u> </u>	<u> </u>		Sta	te	710	Coc				<u> </u>				
C	A	P	I	T	0	L		Н	Ε	I	G	Н	T	S	<u> </u>	<u> </u>		M	D	2	0	7	4	3	Γ.	9	9	9	8
Cor	inty (`ode		ount	. No	ma	<u> </u>	— Д		لـــا		!			<u> </u>	L		- 1		<u> </u>		٠		٢٧					
\bigcirc	2	3	P	R	T IVA	N	С	Ε		G	E	0	R	G	E	S			-						Γ	Ī			
\sim	and the second	and the same of					ress		ins			_	11					_			. ,								*C*LA
				-		- Andrews							5			- 				پختی ن		1,000		17.65					
4	reet 6	or 1-	6	BOX	A	D	D	7	S	0	N		R	0	Α	Ъ		T	ı —		· ·			<u> </u>	r ginesi F	-	<u> </u>		12074
-	17.7		77.	, , ,	A	ע	וח	Ι	D	Щ			T.	0	A	D							100						
	ty or				^	F		77	T2	-	~ [77			_	r		Sta	·	ZIP 2	Coc	le 7	- Ji	2	Γ	Γ_{λ}	Γ	Γ	
С	A	P	I	T	0	\mathcal{L}_{I}	لبا	Η	Ε	I	G	Η	T	S				M	D	2	0	<i>√</i>	4	3	_	9	9	9	8
17	Inst	allat	ion (Cont	act i	Dar	son t	to he	COL	ntaci	ed r	eoar	dine	Y WA	ofa:		itipe	at c	100	1									
· · ·					aut (-		_			7 170	1	CUV	UCG		ne)	4				-	171		15 P. F.	F 4 F 2 10 19 1	7 - 1
-	me	(last)							,		1		, ,,,,	(fir:	st)			ne)										
-			le e un	E	L					, []							Y												
Na	me	(last)							,					(firs	st)	Y			а со	de a	nd n	ımbe	er)					
Na	eme P	(last)	E		S	Т			,					(firs	st)	Y			2	de a	nd m	umb e	e r)	3	3			
Jo VI	p b Ti	(fast A tle H talla) T E tion	E M Co n	L I	S	T	(Se	e in:	struc					(firs	st)	Y					nd m		T	3	3			
Jo VI A. (p b Ti	(lasi A tle H talla) T E tion	E M Con	L I	S		(Se	e in:	struc					(firs	st)	Y					nd ni		T	3	3			
Jo VI A. (p C Ins	(lasi A tle H talla	T E tion	E M Con	L I	S	T	(Se	e in:	struc				S	(firs	st)	Y					nd m		T	3	3			
VI A. (p C Ins	(last	T E tion	E M Con	L I tact	S Add	T lress	(Se	e in:	struc	tions	5)			R Ph	A none	Y	mber	7 (are	2 A	2	-		T	3	3			
VI A. (P C Ins	(last	T E tion	E M Con	L I tact B. \$	S Add	T lress	(Se	e in:	struc	tions	s)	I		R Ph	A none	Y	mbei	7 (are	2 A	2 D	- de		T	3	3	9	9	8
VI A. (C	P C C C C C C A C A	A H talla act /	T E tion Mailir	E M Con ess g	L I tact B. \$	S Add Stree 6	T lress	(See P.O 6	e in:	struc x	tions	b	I	S	R Ph	A none	Y	nbe	7 (are	2 A ZIP	2 D Co	- de	2	2			9	9	8
VI A. C Look	p p bb Tir C C . Insaction X	A tile H talla act /	E tion Addr Mailir	E M Coness ess eg T	I I I I I I I I I I I I I I I I I I I	S Add 6 6 L	T dresset or	(See P.O 6 H	e ins	struc x	tions	b	I	S	R Ph	A none	Y	nbe	7 (are	2 A ZIP	2 D Co	- de	2	2			9	9	8
VI A. C Look	p p bb Tir C C . Insaction X	A tile H talla act /	E tion Addr Mailir	E M Coness ess eg T	I I I I I I I I I I I I I I I I I I I	S Add 6 6 L	T Iress et or 5	(See P.O 6 H	e ins	struc x	tions	D H	I	S	R Ph	A none	Y	nbe	7 (are	2 A ZIP	2 D Co	- de	2	2			9	9	8
VI A. CLOOK	p p p p p p p p p p p p p p p p p p p	(last A A tile H talla act / P P D	E E Addriver I E Ship	E M Conness g T (Sectalla	I I tact B. S 4 O ration T	S Add 6 E L structure L	T fress or 5	H S) Own	e ins . Bo	struc x A	D	D H	I	S	(firs	A none	Y Nur 1	R Sta	r (are	2 A ZIP 2	D Coo	- de	4	3			9	9	8
VI A. CLOOK	p p p p p p p p p p p p p p p p p p p	(fasting A) A title H Hattalla act / I Towner D D A, P. (Casting A)	E E Addr Mallir I ship of Ins	E M Con ess eg T (See	I I I I B. 9 4 O T T Re	S Add 6 E L structure L	T Iresset or 5	H Solution N	e ins Bo	sstruc x A	D	D H	T	S	(first	A none	Y Nur 1	R Sta	r (are	2 A ZIP 2	D Coo	- de	4	3			9	9	8
VI A. (C Loc VI A M S	P bb Tir C . Ins Cont. x y or A I. Ov	(last A) tile H ttalla act / P were D D t, P.c	E tion Addr Mailir ship of Ins	E M Conness g T (Sectalla	I I I I B. 9 4 O T T Re	S Add 6 L L structure L L utte	T fress 5 ction:	H S) Own	e ins Bo	struc x A	D G C	D H	I	S	(firs	A none	Y Nur 1	R Sta M	r (are	A ZIP 2	D Coo	- de 7	4	3			9	9	8
VI A. (C Loc VI A M S	p p cb Tir C C . Ins Contaction X . Nar I . Ov	(last A) tile H ttalla act / P were D D t, P.c	E tion Addr Mailir ship of Ins	M Conness of (Sectalla A	I I tact B. S 4 O e ins T Re A	S Addo Stree 6 L structure L utte D.	T Iresset or 5	H Solution N	e ins Bo	sstruc x A	D G C	D H	T	S	(first	A none	Y Nur 1	R Sta	r (are	A ZIP 2	D Coo	- de 7	4	3 N	C	9			8
VI A. C. C. WI S. C.	P bb Tir C C Ins Cont. A I. Ov Narreet 6 ity o	Towner DD, P.C. 5	E Ition Addr Mailir I Ship Ship Ship I Ship I I Ship I I I I I I I I I I I I I I I I I I I	E M Con ess g (See A Dox, o	I I I I B. 9 I I O I I O I I O O O O O	S Add Street 6 L struct L ute D.	T Iresset or 5	(See P.O 6 H s) Own N hber I.	e ins E E S.	struc x A	D G C N	D H	T F	S	(first R R 3 A A A A A A A A A A A A A A A A A	A none	Y Nur 1	R Sta M H	o te D	A ZIP 2 N ZIP 2 A	D Coo	de 7	1 1 4	3 N	- C	9	9	9	8
VII A. C. C. WI S. 4	P bb Tir C C Ins Cont. A I. Ov Narreet 6 ity o	Towner DD, P.C. 5	E Ition Addr Mailir I Ship Ship Ship I Ship I I Ship I I I I I I I I I I I I I I I I I I I	E M Con ess g (See A Dox, o	I I I I B. 9 I I O I I O I I O O O O O	S Add Street 6 L struct L ute D.	T Iresset or 5	(See P.O 6 H s) Own N hber I.	e ins E E S.	struc x A	D G C N	D H	T F	S	(first R R 3 A A A A A A A A A A A A A A A A A	A none O N	Y Nur 1	R Sta M H	o te D	A ZIP 2 N ZIP 2 A	D Coo O Coo	de 7	1 1 4	3 N	- C	9	9	9	8


OFF Official Use Only	Please print or type with EUTE type (12 characters per inch) in the uns	Isriaded areas only	16.TU
WIII. Type of Regulated Waste Activity (Mark X' in the appropriate boxes. Refer to instructions.) Note A permit of (See Instructions) S. Treater, Storar, Disposer (at Installation) Note A permit is required in the comment of	GENERAL STATE SECTION	ID - For Official Use Only	
Activities Act			The state of the s
1. Generator (See Instructions) 3. Treater: Storer, Disposer (at Installation) 1. Off-Specification Used Oil Fue Mote: A permit is required for his desired of 100 log/mo (22.00 lbs.) 1. (100 1000 lbs			2-1 e 2-1 m/g
Note: A permit is réquired for building processes proc	Hazardous Waste Activity		
A. Characteristics of Nonlisted Hazardous Wastes. Mark X' in the boxes corresponding to the characteristics of nonlisted hazardous wastes your installation handles. (See 40 CFR Parts 261.20 - 261.24) 1. Ignitable 2. Corrosive 3. Reactive 4. EP Toxic (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste n	X a. Greater than 1000kg/mo (2,200 lbs.) Note: A psthis activity	permit is réquired for //ty, see instructions. sus Waste Fuel erator Marketing to Burner er Marketers er Arketers er of Combustion Device . Utility Boiler Industrial Boiler Industrial Furnace a. Generator Marketing to b. Other Markerer c. Burner – indicate device Type of Combustion Device 1. Utility Boiler 2. Industrial Boiler 3. Industrial Furnace 2. Specification Used Oil Fuel (or On-site Burner) Who Fire	Burnei e(s) – volce e Market st Clair
wastes your installation handles. (See 40 CFR Parts 261.20 - 261.24) 1. Ignitable 2. Corrosive 3. Reactive 4. EP Toxic (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (D001) (D002) (D003) (D000) (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number(s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste number (s) for the EP Toxic contaminant (List specific EPA hazardous waste	IX. Description of Regulated Wastes (Use additional sheets	ets if necessary)	
1. Ignitable 2. Corrosive 3. Reactive 4. EP Toxic (10001) (10002) (10003) (10000) (10000) (10002) (10003) (10000) (100	A. Characteristics of Nonlisted Hazardous Wastes, Mark 'X' in the	he boxes corresponding to the characteristics of nonlisted hazardou	IS
X. Certification I certify under penalty of law that I have personally examined and am familiar with the information submitted in and all attached documents, and that based on my inquiry of those individuals immediately responsible obtaining the information, I believe that the submitted information is true, accurate, and complete. I am and that there are significant penalties for submitting false information, including the possibility of fines imprisonment. Signature Name and Official Title (type or print) Date Signed RAY FATEL Chemist 2-28-91	(D001) (D002) (D003) (D000) (List sp. 1000) (List sp. 1000) (List sp. 1000) (D000) (List sp. 1000) (D000) (List sp. 1000) (D000) (List sp. 1000) (D000) (D000) (List sp. 1000) (D000) (D000) (List sp. 1000) (D000) (List sp. 1000) (D000) (D000	ructions if you need to list more than 12 waste codes.) 4 5 6 10 11 12	
I certify under penalty of law that I have personally examined and am familiar with the information submitted in and all attached documents, and that based on my inquiry of those individuals immediately responsible obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aw that there are significant penalties for submitting false information, including the possibility of fines imprisonment. Signature Name and Official Title (type or print) Date Signed RAY FATEL Chemist 2-28-91 XI. Comments	2 3	4 5 6	
I certify under penalty of law that I have personally examined and am familiar with the information submitted in and all attached documents, and that based on my inquiry of those individuals immediately responsible obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aw that there are significant penalties for submitting false information, including the possibility of fines imprisonment. Signature Name and Official Title (type or print) Date Signed RAY TATEL Chemist 2-28-91 XI. Comments			
I certify under penalty of law that I have personally examined and am familiar with the information submitted in and all attached documents, and that based on my inquiry of those individuals immediately responsible obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aw that there are significant penalties for submitting false information, including the possibility of fines imprisonment. Signature Name and Official Title (type or print) Date Signed RAY TATEL Chemist 2-28-91 XI. Comments			
ENDICIPED SICAM COUGHASAH	and all attached documents, and that based on my is obtaining the information, I believe that the submitted that there are significant penalties for submitting fairnersonment. Signature Name and Official	inquiry of those individuals immediately responsible dinformation is true, accurate, and complete. I am a false information, including the possibility of finest light (type or print) Date Signed	le fo awar s an
ENDICIPED SICAM COUGHASAH	XI Comments		
EPA'S TO MINE US a sient permanent		MOISIVE STAN SUUGAAZAM	
	riease issue us a	new permanent	
FOOI & SAM			



ACKNOWLEDGEMENT OF NOTIFICATION OF HAZARDOUS WASTE ACTIVITY

(VERIFICATION)

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act(RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.



EPA Form 8700-12B (4-80)